

Average Vehicle Count

Technician Name: administrator

Location: Tamarack Dr.
 Address: 413 Tamrack Dr., South Bethany, DE, USA, 19930
 Speed Limit: 20

Report Period: 05/30/2016 to 06/12/2016
 Total Vehicle Count: 15,058



Hour	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday	Average Weekday	Average Weekend	Average Week	Average Speed	85% Speed
00-01	12	7	9	2	7	8	10	7	9	8	18	5
01-02	1	2	2	0	0	5	3	1	4	2	17	5
02-03	4	2	0	0	1	4	2	1	3	2	17	5
03-04	1	6	3	0	0	4	0	2	2	2	21	5
04-05	1	2	2	2	2	0	0	2	0	1	22	5
05-06	10	7	2	3	2	7	2	5	5	5	19	5
06-07	16	10	12	13	15	14	15	13	15	14	18	5
07-08	48	40	42	27	32	42	32	38	37	38	17	5
08-09	62	68	55	58	74	77	50	63	64	63	16	5
09-10	76	74	64	51	82	76	66	69	71	70	16	4
10-11	84	72	60	56	81	76	86	71	81	74	16	4
11-12	^H 112	98	91	70	92	100	78	93	89	92	16	5
12-13	98	90	86	102	^H 102	90	78	96	84	92	16	5
13-14	98	80	76	88	83	87	78	85	83	84	16	4
14-15	84	91	85	89	^H 102	78	63	90	71	85	16	4
15-16	96	104	100	94	94	^H 106	78	98	92	96	16	4
16-17	91	^H 138	^H 106	^H 124	96	84	^H 90	111	87	104	17	5
17-18	69	94	83	72	90	96	58	82	77	80	17	5
18-19	44	38	47	42	80	66	48	50	57	52	17	4
19-20	44	37	36	40	51	61	40	42	51	44	16	5
20-21	22	16	28	23	37	36	26	25	31	27	16	4
21-22	12	16	9	20	32	38	15	18	27	20	17	5
22-23	8	9	18	16	19	16	12	14	14	14	17	5
23-24	4	10	5	6	9	18	3	7	11	8	16	4
TOTAL:	1,097	1,111	1,021	998	1,183	1,189	933	1,083	1,065	1,077	17	5