

# Average Vehicle Count

Technician Name: administrator

Location: Tamarack Dr.  
 Address: 413 Tamrack Dr., South Bethany, DE, USA, 19930  
 Speed Limit: 20

Report Period: 05/27/2016 to 05/31/2016  
 Total Vehicle Count: 6,726



Hour	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday	Average Weekday	Average Weekend	Average Week	Average Speed	85% Speed
00-01	18	9	n/a	n/a	n/a	8	28	14	18	16	17	5
01-02	2	4	n/a	n/a	n/a	14	7	3	11	7	17	5
02-03	7	5	n/a	n/a	n/a	0	5	6	3	4	20	5
03-04	0	10	n/a	n/a	n/a	10	1	5	6	5	20	5
04-05	0	3	n/a	n/a	n/a	0	2	2	1	1	21	5
05-06	9	14	n/a	n/a	n/a	2	5	12	4	8	18	5
06-07	25	15	n/a	n/a	n/a	15	32	20	24	22	17	5
07-08	51	45	n/a	n/a	n/a	67	67	48	67	58	16	4
08-09	40	82	n/a	n/a	n/a	107	76	61	92	76	15	4
09-10	82	76	n/a	n/a	n/a	131	112	79	122	100	16	4
10-11	90	92	n/a	n/a	n/a	166	126	91	146	119	16	4
11-12	<sup>H</sup> 159	85	n/a	n/a	n/a	116	110	122	113	118	15	4
12-13	113	82	n/a	n/a	n/a	114	123	98	119	108	16	4
13-14	97	82	n/a	n/a	n/a	130	111	90	121	105	16	4
14-15	86	89	n/a	n/a	65	129	140	80	135	102	16	4
15-16	81	113	n/a	n/a	159	114	<sup>H</sup> 191	118	153	132	16	4
16-17	83	<sup>H</sup> 185	n/a	n/a	<sup>H</sup> 170	144	129	146	137	142	16	5
17-18	72	106	n/a	n/a	117	<sup>H</sup> 189	168	98	179	130	16	4
18-19	45	27	n/a	n/a	75	106	114	49	110	73	16	4
19-20	50	44	n/a	n/a	89	47	90	61	69	64	16	4
20-21	25	n/a	n/a	n/a	62	64	81	44	73	58	16	4
21-22	17	n/a	n/a	n/a	49	39	38	33	39	36	16	4
22-23	7	n/a	n/a	n/a	23	37	24	15	31	23	17	5
23-24	3	n/a	n/a	n/a	21	14	23	12	19	15	16	4
<b>TOTAL:</b>	<b>1,162</b>	<b>1,168</b>	<b>0</b>	<b>0</b>	<b>830</b>	<b>1,763</b>	<b>1,803</b>	<b>1,307</b>	<b>1,792</b>	<b>1,522</b>	<b>17</b>	<b>4</b>