

# Statistics Summary Report

Technician Name: administrator

Location: Tamarack Dr.  
 Address: 413 Tamrack Dr., South Bethany, DE, USA, 19930  
 Speed Limit: 20

Report Period: 05/27/2016 to 05/31/2016  
 Total Vehicle Count: 6,726



Hour	Total Vehicles	Average Vehicles	Total Violations	% Violations	Min. Speed	Max. Speed	Avg. Speed	85% Speed
00-01	63	16	10	16 %	8	22	17	5
01-02	27	7	7	26 %	7	24	17	5
02-03	17	4	7	41 %	11	34	20	5
03-04	21	5	9	43 %	9	27	20	5
04-05	5	1	3	60 %	17	23	21	5
05-06	30	8	6	20 %	9	24	18	5
06-07	87	22	14	16 %	4	24	17	5
07-08	230	58	27	12 %	3	25	16	4
08-09	305	76	22	7 %	4	25	15	4
09-10	401	100	42	10 %	3	25	16	4
10-11	474	119	34	7 %	3	24	16	4
11-12	470	118	50	11 %	3	28	15	4
12-13	432	108	54	13 %	4	25	16	4
13-14	420	105	55	13 %	4	25	16	4
14-15	509	102	74	15 %	3	32	16	4
15-16	658	132	69	10 %	3	26	16	4
16-17	711	142	112	16 %	3	30	16	5
17-18	652	130	69	11 %	3	27	16	4
18-19	367	73	35	10 %	4	27	16	4
19-20	320	64	39	12 %	3	27	16	4
20-21	232	58	18	8 %	4	23	16	4
21-22	143	36	17	12 %	3	24	16	4
22-23	91	23	15	16 %	3	22	17	5
23-24	61	15	9	15 %	3	26	16	4
	<b>6,726</b>	<b>1,522</b>	<b>797</b>	<b>18 %</b>	<b>5</b>	<b>26</b>	<b>17</b>	<b>4</b>

Count by Speed Bins

Speed	Count
0...5	107
5...10	631
10...15	2,128
15...20	3,063
20...25	772
25...30	23
30...35	2
<b>Total:</b>	<b>6,726</b>